


Termination

Strip off at least 1.2" of jacket from end of cable.










Cutting Module Assembly



Handle Lock

